

Lauren Dorsey
10975 Birch Dr
Denver, CO 80233

Ph# :(727) 776-0253

ESTIMATE ONLY

Qty.	Part Number	Description	Tech	Each	Core	Total
Inspection						
1	INS-05100I	Brake Inspection		\$ 0.00	\$ 0.00	\$ 0.00
1	INS-05299I	All Inspections		\$ 0.00	\$ 0.00	\$ 0.00
Inspection: Subtotal						\$ 0.00
Rear Brake Service						
1	CPW-PXD835H	Premium Brake Pad Set		\$ 99.00	\$ 0.00	\$ 99.00
-	LAB-05102LR1	Premium Complete Rear Brake Service	14319	-	-	\$ 120.99
Rear Brake Service: Subtotal						\$ 219.99
Rear Caliper(s)						
1	A1C-19-B2950	CALIPER W/BRCKT		\$ 185.99	\$ 0.00	\$ 185.99
1	A1C-19-B2951	CALIPER W/BRCKT		\$ 185.99	\$ 0.00	\$ 185.99
-	LAB-05117	Rear Brake Caliper(s)	14319	-	-	\$ 129.00
Rear Caliper(s): Subtotal						\$ 500.98
Rear Rotor(s)						
2	CWD-YH145293	BRAKE ROTOR		\$ 63.99	\$ 0.00	\$ 127.98
Rear Rotor(s): Subtotal						\$ 127.98
Brake Flush						
-	LAB-051144	Flush Brake System - DOT 4	14319	-	-	\$ 50.00
1	FT-FT50100	Dot 4 Brake Fluid (QT.)		\$ 19.99	\$ 0.00	\$ 19.99
Brake Flush: Subtotal						\$ 69.99
Subtotal						
\$ 0.00						\$ 0.00

NOTES : -Rear brake pads are at 0%
-Rear rotors have over heated due to caliper sticking
-Rear calipers are stuck due to rust
Recommended to replace calipers, brake pads and rotors due to safety concerns

ESTIMATE / PREVIEW ONLY - NOT VALID FOR WARRANTY

ESTIMATE ONLY / DO NOT PAY.

Your Brakes Plus General Manager is:
Tony Smith @ 303-457-2300 1300 E 104th
Ave Thornton CO 80233

Vehicle Information

Vehicle : 2006,SCION,tC,4-2362 2.4L
DOHC,JTKDE177460120932
License # : QCFN82
Miles : 201062
V.I.N. : JTKDE177460120932
Unit # :

DEPARTMENT	SALE
Labor	\$ 299.99
Disposal Labor	\$ 2.00
Parts	\$ 618.95
Fluids/Supplies	\$ 29.87
SUB TOTAL	\$ 950.81
SALES TAX	\$ 55.15

ESTIMATE AMOUNT \$ 1005.96